

ECS/EMD Configuration Change Request

Page 1 of

Page(s)

1. Originator Maryellen Corbett	2. Log Date: 02/16/04	3. CCR #: 04-0109	4. Rev: —	5. Tel: 301 925-0703	6. Rm #:	7. Org. COTS
8. CCR Title: Solaris 8 Patch Baseline Update - Feb. 2004						
9. Originator Signature/Date Maryellen Corbett /s/ 02/16/04			10. Class II	11. Type: CCR	12. Need Date: 02/28/2004	
13. CCR Sponsor Signature/Date Pamela Johnson /s/ 02/16/04			14. Category of Change: Update ECS/EMD Baseline Doc		15. Priority: (If "Emergency" fill in Block 27). Routine	
16. Documentation/Drawings Impacted (Review and submit checklist): See attached page			17. Schedule Impact:		18. CI(s) Affected:	
19. Release Affected by this Change: EMD		20. Date due to Customer:		21. Estimated Cost: None - Under 100K		
22. Source Reference: <input type="checkbox"/> NCR (attach) <input type="checkbox"/> Action Item <input type="checkbox"/> Tech Ref. <input type="checkbox"/> GSFC <input type="checkbox"/> Other:						
23. Problem: (use additional Sheets if necessary) Some baseline inconsistencies have been identified. These may involve baseline updates and/or installation/removal of COTS products to resolve identified baseline inconsistencies.						
24. Proposed Solution: (use additional sheets if necessary) Provide baseline red-lines and/or ECOs to resolve identified discrepancies. Attached sheet provides summary of baseline and system administration changes. These changes are also included in the ECO instructions for resolution of identified baseline discrepancies.						
25. Alternate Solution: (use additional sheets if necessary) Accept an inconsistent baseline and installations						
26. Consequences if Change(s) are not approved: (use additional sheets if necessary) Inconsistent baseline and installations						
27. Justification for Emergency (If Block 15 is "Emergency"):						
28. Site(s) Affected: <input type="checkbox"/> EDF <input checked="" type="checkbox"/> PVC <input type="checkbox"/> VATC <input type="checkbox"/> EDC <input type="checkbox"/> GSFC <input type="checkbox"/> LaRC <input type="checkbox"/> NSIDC <input type="checkbox"/> SMC <input type="checkbox"/> AK <input type="checkbox"/> JPL <input type="checkbox"/> EOC <input type="checkbox"/> IDG Test Cell <input type="checkbox"/> Other						
29. Board Comments:			30. Work Assigned To:		31. CCR Closed Date:	
32. SCDV CCB Chair (Sign/Date): Byron V. Peters /s/ 2/19/04			Disposition: <u>Approved</u> App/Com. Disapproved Withdraw Fwd/ESDIS ERB Fwd/ECS			
33. EDF CCB Chair (Sign/Date):			Disposition: Approved App/Com. Disapproved Withdraw Fwd/ESDIS ERB Fwd/ECS			
34. ECS CCB Chair (Sign/Date):			Disposition: Approved App/Com. Disapproved Withdraw Fwd/ESDIS ERB Fwd/ESDIS			

ADDITIONAL SHEET

CCR #: 04-0109 **Rev:** — **Originator:** Maryellen Corbett

Telephone: **Office:**

Title of Change: Solaris 8 Patch Baseline Update - Feb. 2004

CM Documents:
920-TDP-014: PVC Patch Map

Baseline Documentation updates ONLY:

1. Add PTF773146 and PUT0203 to the OS patch baselines of:
 - a. p0drs03
 - b. p0drs05
2. Patches 108711-04, 108734-02, 108735-03 are not currently baselined, but are installed on some Sun machines. These patches are not currently delivered patches, and are detected only on the older Sun machines in the PVC. Newer installations do not have this patch. It is recommended that this legacy patch be baselined, as it was not removed in the original Solaris 8 upgrade and maybe still required for the older sun hosts: Add these patches to the following machines that are still baselined: p0ais01, p0css02, p0ins02, p0mss07, p0mss21, p0tes02, p0tes03, p2acs03, p2ins03, p2pls02 and p2sps06.
3. A few patches are installed on machines that had an early delivery of Solaris 8 and were then upgraded to the current patch baseline. Some undocumented patches were installed or not uninstalled in this process. It is recommended that these be baselined, as this installation is consistent across all of these hosts in the PVC. These hosts have been running on this baseline for over a year without incident. On p0drs03, p0drs05 and p0sas01, add the following patches to the patch baseline:
 - a. 108914-02: SunOS 5.8: l10n update: PDA Sync, SmartCard, DHCP mgr, Printer Adm
 - b. 108954-02: SunOS 5.8: localization updates for different components
 - c. 110274-03: SunOS 5.8: Figgs Custom install new features and install help
 - d. 110797-02: SunOS 5.8: UR4 New int
 - e. 110888-01: SunOS 5.8 : figgs, New and updated message strings
 - f. 111275-01: SunOS 5.8: New features Solaris 8 Update 5 European
 - g. 111823-01: SunOS 5.8: New features UR6 European Support
 - h. 112183-03: SunOS 5.8: translations for s8u7
 - i. 112334-01 SunOS 5.8: archsystem.h patch
4. Replace 112334-02 with patch 112334-01 in the baseline for p0drs03, p0drs05 and p0sas01 as indicated above.
5. Remove patch 112279-02 from the baseline of all PVC Sun hosts, as this patch is not installed on any PVC host. It is assumed that this is a documentation error that needs to be corrected or patch may have been delivered, but was not installable on any EMD Solaris hosts.
6. CCR 03-0607A identified that the following patches should be installed on p2acs06 and p2ins02.

109962-07	Hardware, FC-AL Disks; Download program and FC-AL Disk Driver firmware
112186-08	Hardware/PROM: Sun Fire V880 Flash PROM Update

These patches were delivered with the other V880 patch bundle, but were not valid patches for the specific hardware implementation and therefore were not loaded. These patches should be removed from the patch baseline of these machines under these circumstances.

Infrastructure ECOs:

1. Patch 108528-21 was identified for installation on p0sas01 in CCR 03-0690. Patch 108528-23 is currently installed. Remove patch 108528-23 and install 108528-21 to resolve baseline discrepancy.
2. Patch 108813-12 was the baseline for all Sun hosts except p0sas01 as specified in CCR-03-0690. P2acs06 and p2ins02 have a higher revision of this patch installed (108813-15). Remove 108813-15 and install the baseline patch 108813-12.